

Wahl DST 600

Advantages and Disadvantages to Other Technologies



Features	Wahl DST 600 RTD	Thermocouple	Bi-Metal	Spirit Filled Industrial Thermometers
Problem using as a MIG Replacement	See below	See below	Friction causes inaccurate reading, especially All Angle versions.	Not linear. Large bore is affected by ambient temperature. Separates easily.
Long Term Stability	Excellent	Good	Fair	Good
Accuracy	Excellent	Good	Fair	Fair
Repeatability	Excellent	Good	Fair	Good
Sensitivity (readability)	Excellent	Good	Fair	Good
Response	Good	Excellent	Good	Poor
Linearity	Excellent	Good	Fair	Poor